

Please solder one end, then let it cool. Only then, solder the other end.

Positive DC line to be connected this way:



From DC power source.

Note direction of arrow!

Neutral (return) line to be connected this way:



From load (circuitry).

Note direction of arrow!