

Firewall Robusto™


CONNECTION RULES FOR SPEAKER SIGNAL APPLICATIONS

DIY version for Self-installation

CONNECTION SCHEMATICS

This unit conditions the current for **ONLY ONE** polarity.

You need four units to condition Left Positive, Left Negative, Right Positive, and Right Negative polarities. Note **arrow** direction for each unit.



This is 6mm², a large iron is recommended. (We use 150 Watts.) Simply solder over the red markings; they will not interfere. Use ample flux. This copper is highly treated. Oxides are normal and per design. Scrape clean before soldering. Arrow on the side always points towards the red markings.